Documents Information(2026-09-11 ~ 2026-10-10)

No	Document Name	Version	Release Date	Description	Revirsion History	Source
1	GPL81408A EMU Board User Manual	1.1	2026/9/15		1. Added the EMU Board V1.1 comparison list to Chapter 1.2. 2. Added EMU Board V1.1 sections: Overview, Circuit, and PIN Options (Chapters 2.3, 2.4, and 3.3).	Sales contact
2	GPL98103UA Data Sheet	1.1	2026/10/1			Website
3	GPL98100UA Data Sheet	1.4	2026/10/1			Website
4	GPLB62150A Pad Assignment and Locations	1.2	2026/10/1		Modify pad diagram.	Sales contact
5	GPL98103UA EMU Board User Manual	1.0	2026/10/2			Sales contact
6	GPM32F13X7 Preliminary Data Sheet	0.1	2026/10/2			Website

Generalplus

Tools Information(2026-09-11 ~ 2026-10-10)

No	Tool Name	Version	Release Date	Description	Revirsion History	Source
1	Keil MDK ICE Driver	V1.0.4	2026/9/14	MDK ICE Driver for developing GPM32/GPCM project by using keil MDK IDE	- Support GPM32F1117RL, GPM32F1116CL, GPM32FD0338B,GPM32F1206CL, GPM32F1205CL, GPM32F1117RLQ, GPM32F9010RL, GPM32F9010RLQ,GPM32F1306CL, GPM32F1307CL, GPM32F1405KV, GPM32F1317HG - Remove GPM32F6006U, GPM32F6006V - Fixed up crash when failed to get BOM pointer from KEIL. - Fixed up crash during download. - Fix Fill-in CRC failed. - G+Link Pro FW V3.0.3.3	Website
2	G+ IDE for RISC	2.0.9	2026/9/17	The G+IDE for RISC is a Generalplus Integrated Development Environment for RISC series development. This IDE has Microsoft Visual Studio-like Ul for easy control. It is composed of the application workspace and the work platform, assembly language, features programmindg development. The fiendly interface will assist you to developing your programmer more easily and efficiently.	- Add body: GPC74F510A body. (include all SOP bodies for QPS project) - Add body option of IR Duty&Frequecy: "1/2 Duty, 111.11KHz" for GPC71PxxxB1, GPC72PxxxC, GPC72PxxxD, GPC74PxxxB1, GPC74PxxxC, GPC74PxxxD series. - Enable 1Mhz option for GPC71P080B1, GPC74P080B1 bodies. - Add IRDuty option in MaskOptions section for QPS project. - Fixed QPC wizard code generate fail with some chinese characters in source code. - Fixed QPS Wizard crash issue while Table over 16 items. - Fixed QPS Wizard crash issue while Table is empty.	Website